
THIS INSTRUCTION SHEET APPLIES TO PLUG FA42256 USED WITH CONTACTS KT41236 OR KT41236-02.

ASSEMBLY INSTRUCTIONS:

- 1- STRIP WIRE INSULATION TO EXPOSE .060-.090" [1.53-2.28 mm] OF WIRE CORE. INSERT STRIPPED WIRES THROUGH SKID WASHER AND REAR INSERT. CRIMP WIRE TO CONTACTS. CRIMP USING FP41735 CRIMP TOOL (CRIMP SETTING 5) WITH FP41731 LOCATOR.
- 2- AFTER CRIMPING SEAT CONTACTS INTO REAR INSERT.
- 3- INSERT REAR INSERT INTO FRONT INSERT MAKING SURE THE CONTACTS HAVE FULLY SEATED INTO THE FRONT INSERT. THIS IS VISUALLY CONFIRMED WHEN THE SHOULDERS ON BOTH INSERTS ARE NEARLY TOUCHING.
- 4- INSTALL INSERT ASSEMBLY INTO COUPLING NUT, THEN INSTALL SKID WASHER AND RETAINING RING INSIDE COUPLING NUT.
- 5- CONTACTS ACCEPT A 28-32 AWG WIRE SIZE FOR CRIMP.
- 6- MAXIMUM WIRE INSULATION OD: .030" [0.76 mm]



PROPRIETARY AND CONFIDENTIAL

THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF SOLID SEALING TECHNOLOGY, ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT THE WRITTEN PERMISSION OF SOLID SEALING TECHNOLOGY IS PROHIBITED.



INSTRUCTION SHEET
MICRO C PLUG ASSEMBLY

557					_				N
	Т	Е	C	Н	Ν	0	L	0	G

REV	. APP	D DATE	SCALE 1.5:1	DIMENSIONS IN	DRAWN	JF	3/29/2021	NUMBER:	REV:	SHEET 1 OF 1
С	JF	08/06/2021	MSPLR004-55WS	INCHES [mm]	ENG APPR.	JF	3/29/2021	NS42256		SHLLI I OI I